

Nº 5804

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-25-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1128

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 65'
CURB LINE AND DEPTH 6' deep

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

11TH ST N.E.

12

6' deep

5'

0'

6' deep

8'

65'

11TH ST N.E.

SIGNED

John Elmer
INSPECTOR FOR CITY

Rotch Ave N.E.

FILED AT ENGINEER'S OFFICE

5/17/52

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5804

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/13 1921RECEIVED OF Harry SchauerFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED ✓ Harry SchauerTO TAP SanitarySEWER, ON THE EastOF 11th St NEAVE., TYPE OF STREET pavedTHE PREMISES BEING LOT NO. 7474HOUSE NO. 1128

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Diana

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.