

9-71

No 5811


FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-11-52IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. 1024SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHWAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN YesNAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N. ←

Eng. Dept. Record
shows 4' pipe
from Y on main
where lateral
was connected.

SIGNED R. J. Snyder
INSPECTOR FOR CITYFILED AT ENGINEER'S OFFICE 6-27-52

REMARKS:

Nº 5811

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6-12-52 19

RECEIVED OF ~~James J. Land~~ D. Land

FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED J. Chesby Land Co

TO TAP San

SEWER, ON THE east

OF 8th N. E

AVE., TYPE OF STREET slit

THE PREMISES BEING LOT NO. 7557

HOUSE NO. 1024

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR D. Land

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.