## Nº 5831

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED	8-4-52	FIRST MANHOLE DOWN STREAM Stub 171 Manhole
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CU		NAME OF CONTRACTOR L. Albrecht
SHOW BY DIAGRAM R		RAL TO WALL OF BUILDING SERVED.
		Ma
all with the approximation of the	in the their winds which	Company of the second of the s
4	y see	
SIGNED ALLOY	TINSPECTOR FOR C	TY TO THE POST OF THE AT ENGINEER'S OFFICE 9-23-53

## Nº 5831

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	i wanini sanga wana kata kata ke Bilik ingga wani sani mini intah Bilik ingga salah sani kaji Andoni j	Massillon, Ohio,	<b>July 3</b> 0
RECEIVED OF Garson I	and the second s		
ៀមអៀមៀល ប្រ. ក្រុម ខេត្ត ខេត្ត មាន មាន មាន ស្ត្រាំ ប្រ. ដ	ទី៣ ៩០០លីខាទ្ធីហ្វេទី៩៩៩០០៩៦ ។ ១៩០១០ <u>ទី</u> ទី៩ 🚅 ១៩១៩១		
TO TAP Sanitary		N THE Bast	
		TA	
THE PREMISES BEING LOT NO. 108		•	440
Work to be done in accordance	WITH ORDINANCE	No. 2323, DULY PA	SSED BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBL			

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.

L. Albrecht