Nº 5842

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED $8-8-52$	IF SO HOW AND LOCATION FROM TIRST MANHOLE DOWN STREAM
HOUSE NO. 427	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE. NO C. VERTICAL DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	Company of the constraint of the second of t
WAS ATTACHED TO MAIN 185	NAME OF CONTRACTOR L. 17 16 VO C ht
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	7' 3'deed
relate to the compared to the	Mark Mark Mark Mark Mark Mark Mark Mark
A.	Grosvenord 7'17'dup
en e	7/ 7/ 10 DV (ABO 10 DO 14:15)
SIGNED LEVEL Southon	FILED AT ENGINEER'S OFFICE 9-2-53
REMARKS:	Chalifernika ad tomisles de a latinsi de allani.

N_{\cdot}^{0} 5842

PERMIT TO TAP SEWER

		Massillon, Ohio,	July 30
RECEIVED OF Garson P			
FOR WHICH PERMISSION IS GRANTE	, Same		
TO TAP Sen Itary	SEWER	ON THE West	
or Cerver NW	- 第二次 1994年 - 1994年 - 日本の大学 1997年 - 1994年 -	OF STREET Dir	
THE PREMISES BEING LOT NO. 109		, HOUSE NO.	그는 그는 사람들을 본 때 그
WORK TO BE DONE IN ACCORDANC			
RULES OF THE DEPARTMENT OF PUB		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

L. Albrecht