## Nº 5847

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-7-5	2 IF SO HOW AND LOCATION FROM /// 30'
HOUSE NO. 701	DISTANCE FROM FIRST MANHÖLES  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO WAS ATTACHED TO MAIN YE SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.
	13' deep
e en la principion de la companya d La companya de la companya della companya del	By sidup Czrver
SIGNED LING COOR F	FILED AT ENGINEER'S OFFICE 8-19-53

## Nº 5847

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		Massillon, Ohio,	A STATE OF THE STA	
RECEIVED OF <b>Cars</b>	• •	,	The same of the sa	, 2.0
FOR WHICH PERMISSION IS GR	ANTED Same			
		r, on the $rac{West}{}$		
or Carver NW		e of street Dirt	s el lugión Mila .	
THE PREMISES BEING LOT NO		, HOUSE NO,		
WORK TO BE DONE IN ACCOR				Council
RULES OF THE DEPARTMENT OF		•		

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.