## Nº 5850 AND SIGNED WHEN RETURNED. AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-7-52	FIRST MANHOLE DOWN STREAM
HOUSE NO 505	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE.  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURBY /YO	n de la california y de Tela en de l'entresa en la estanta en 49. La california
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR Albrecht
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	N i and a similar was regular to a significant
	(3'deip Main
	The state of the control of the state of the
	91 5'desp & C21
a a da a	
SIGNED ALCO CONTRACTOR	FILED AT ENGINEER'S OFFICE 8-19-53
NSPECTOR FOR CI	Y arditerate of resident is their the filtery
REMARKS:	

## Nº 5850

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		Massillon, Ohio,_	July 30	
RECEIVED OF Garson	<u> Paige Cons</u>	truction C	ompany <sub>Fee</sub>	or <b>s</b> 2.
FOR WHICH PERMISSION IS GRANTED	::::::::::::::::::::::::::::::::::::::	Depth of the second of the sec	I ki terba	
TO TAP Sanitery		on the Wes		
or Carver III		The second second		
THE PREMISES BEING LOT NO. 10979	,	HOUSE NO		
WORK TO BE DONE IN ACCORDANCE	, 4	70	•	
RULES OF THE DEPARTMENT OF PUBL	·		LASSES BY INE	
Name of Contractor L. All	recht	•		3000

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.