Nº 5854

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-11-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 476	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	and the state of t
	NAME OF CONTRACTOR L. Albrecht
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
ere di parti par las las especiales per la companya de la companya de la companya de la companya de la company La companya de la co	12 deepons in which are made Main Sewer
SIGNED LEVY douther	41' Grosve Nov
INSPECTOR FOR C	27 Garage Marited at Engineer's Office 9-2-53

Nº 5854

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

接着的 医甲基氏管性 医自己性病病 医二氏病 电路电路	e e e e e e e e e e e e e e e e e e e	4.00 9.3	ily 30
RECEIVED OF Garenn Pai		· Comment of the second of the	
RECEIVED OF (12787) 22	To see a		
TO TAP SANITE -		ere a Fig. Discourter outgroup to be that of the material	14 1 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
of Grosvenor NW			
THE PREMISES BEING LOT NO. 10274	•		
WORK TO BE DONE IN ACCORDANCE WIT	and the second of the second o	. 2323, DULY PASSE	D BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC S	ERVICE.		

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.