Nº 5860

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED_		O HOW AND LOCATION FROM 11 VII 2/3
HOUSE NO.	501	MANAGE BOWN BIREAM
SIZE OF PIPE USED	6 DOW	FANCE FROM FIRST MANHOLE CONTROLS VN STREAM TO DITCH AT RB LINE AND DEPTH
WAS LATERAL AT CI	JRB7// 0	Childian and the track the second was the second
WAS ATTACHED TO	MAIN YES NAM	ME OF CONTRACTOR
SHOW BY DIAGRAM	RELATION OF LATERAL T	TO WALL OF BUILDING SERVED.
		71
	and an institution of the second and	Mainsewer /3'deep
entri viljo entri vil en e entri	u s policina i postata le 11 mis ses	The state of the second
		2 41/ 3'6" clus
		2/3'

Nº 5860

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	dia ne valte de la Nationalia e Mai	SSILLON OHIO	July 30
	e never to the second		
RECEIVED OF Gran	Deima Constru	ertion Compa	nv 2.0
		· · · · · · · · · · · · · · · · · · ·	FEE OF STREET
FOR WHICH PERMISSION IS GRANTED	Same		
TO TAP Senitor;	eruen est	Woot	And the second s
		The state of the s	
or Grosvenom NV	AVE. TYPE OF	STREET	Dirt
and the contraction of the contr	ST.,		
THE PREMISES BEING LOT NO. 11C	900	, HOUSE NO	501.
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
WORK TO BE DONE IN ACCORDANCE	WITH ORDINANCE NO	. 2323. DULY PASS	ED BY THE CITY COUNC
RULES OF THE DEPARTMENT OF PUBL	- to the second of the second	1985 1985	

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.