\mathbf{N} ° 5889

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED /0-23	52 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 503	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	na a la california de la compansión de la c Transportación de la compansión de la comp
WAS ATTACHED TO MAIN YES	MAINE OF CONTINACTOR
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.
i ligita di mangangan kang menggan penggan ang Al aban . Menggan kanggangan penggan pen	A 3'deepo
	in the contract appoint to the property of the contract of the
	0 1031 /3'deep
9 4 5 4	
SIGNED INSPECTOR FO	FILED AT ENGINEER'S OFFICE 12-22-53
REMARKS:	pois notineally a residue si phiblical be ellaw a company of the company

Nº 5889

PERMIT TO TAP SEWER

	 Section of the section of the section	ter som og er er og v Til store for er er er Til store	MASSILLO	и, Онго,	July	30 1
R	ECEIVED OF Garson I	Paige Cons	tructi	on Compan	Y FEE C	F 52
	CH PËRMISSION IS GRANTED	San e			jante, e č	
	•					8 M. F. T. F. 11 1.
то тар	Senitary	SEWER,	ON THE	W	est	
OF	Standish NW	AVE., TYPE	1.15	Takan Kabupatèn Pala		
THE PREM	AISES BEING LOT NO. 11031			HOUSE NO.		
WORK TO	D BE DONE IN ACCORDANCE V	VITH ORDINANCE	No. 232	3, DULY PASSED	BY THE C	ITY COUNC
Rules o	F THE DEPARTMENT OF PUBLIC	SERVICE.	•			
	— T A 13					27.5

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.