

Nº 5893

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-15-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1515

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Byron Ave S.W.



SIGNED

[Signature]

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8/14/52

REMARKS: _____

Nº 5893

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 31 1

RECEIVED OF Geo Hastler FEE OF \$

FOR WHICH PERMISSION IS GRANTED Geo Hastler

TO TAP Sanitary SEWER, ON THE South

OF Bryant St W AVE., TYPE OF STREET hard surface

THE PREMISES BEING LOT NO. 8143, HOUSE NO. 1515

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR P Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.