

Nº 5895

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-8-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 822

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

202

7' 6" deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Milburn Rd. NE



SIGNED

J. Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8/14/52

REMARKS:

Nº 5895

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

Aug 8 1

RECEIVED OF

A. D. Leaking

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

A. D. Leaking

TO TAP

Saint

SEWER, ON THE

South

OF

Millman NE

AVE.
ST.

TYPE OF STREET

gravel

THE PREMISES BEING LOT NO.

5053

HOUSE NO.

822

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Paul Hamer

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.