## **Nº** 5900

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

	•		
DATE INSPECTED 6-24-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		· ·
HOUSE NO. 2558			
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	98'	7.6" def
WAS LATERAL AT CURBY		the form of the second of	
WAS ATTACHED TO MAIN VAS	NAME OF CONTRACTOR	Diana	
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SE	RVEQ.	
Harsh Al	re.5E	1	4
and the state of t		14	6 deg
		l by	5
arras de la companya			
		3	
		78	170%
en ja variante en	and a control of the		4
1 6			The state of the s
SIGNED LEADING	FILED AT EN	GINEER'S OFFICE	8/15/53
INSPECTOR FOR CIT			
REMARKS SEWEL ON 2.	ITH ST. S.E.	The second secon	

## Nº 5900

## PERMIT TO TAP SEWER

	/ED OF	MAE	SSILLON, OHIO, 8	
FOR WHICH P		aim.	Aldresial	FEE OF S
TO TAP	anitan	SEWER, ON T	HE NW C	nner
OF Was	abde	AVE., TYPE OF !	STREET Oil	
THE PREMISES	BEING LOT NO. 69	39	, HOUSE NO	2558
	DONE IN ACCORDANCE W		2323, DULY PASSED	BY THE CITY COUN

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.