## Nº 5903

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-18-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1425	DISTANCE FROM FIRST MANHOLE.  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	4 deep
WAS LATERAL AT CURBY YES		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIRECTOR	
SHOW BY DIAGRAM RELATION OF LATE  Walnut R	1.5.W.	
erander en		<b>%</b>
	1 249	a 98
SIGNED 1. Ehmu	FILED AT ENGINEER'S OFFICE	
INSPECTOR FOR CIT	TY STATE OF THE PROPERTY OF T	

## Nº 5903

## PERMIT TO TAP SEWER

gin statut da visita de la companya	MASSIL	LON, OHIO,	132
RECEIVED OF CO L	and		FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED	nike	Dun	nel
TO TAP_ Landow	_sewer, on THE_		uÅ
OF Walnut SW AN	E. TYPE OF STRI	EET	elect
THE PREMISES BEING LOT NO. 4/74/		., HOUSE NO.	1425
WORK TO BE DONE IN ACCORDANCE WITH O	RDINANCE NO. 23	323, DULY PASSE	D BY THE CITY COUNC
RULES OF THE DEPARTMENT OF PUBLIC SERVICE	•	e grande de la companya de la compan	
a9 50.	end.		·

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.