

Nº 5906

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-16-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1809

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 269' 6' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

STONER AVE N E



SIGNED _____

J. Chesser
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

8/14/52

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 5906

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/7RECEIVED OF A. G. DianaFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Jacob GlickTO TAP SanitarySEWER, ON THE SouthOF FlowerAVE.,
ST.,TYPE OF STREET dirtTHE PREMISES BEING LOT NO. 8074, HOUSE NO. 1809

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. G. Diana

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.