Nº 5907

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-9-52	IF SO HOW AND LOCATION FROM 38	8' Deep
HOUSE NO. 8/0 860	<u></u>	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	<u>a de la Catalla de Arresto de la la persona aborda.</u>	d de
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Diana	
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.	· / /
Milburn	Rd. NE	13
		[/ R ye
ing Talang. Pengalagan di kecamatan pengalagan di Malangan Salangan Salangan Salangan Salangan Salangan Salangan Salangan	A STATE OF THE STA	101
	to a securit in part and a second second are as second by the first second seco	
	0 35.	1/30
SIGNED O Show		ENDORLINE
INSPECTOR FOR	CITY THE BUT OF THE B	8/1452

Nº 5907

PERMIT TO TAP SEWER

	MASSILLON, OHIO, 8/12/52
27	RECEIVED OF 19 1 Anna FEE OF \$ 2
* ~	FOR WHICH PERMISSION IS GRANTED WILLIAM 77)
	TO TAP SEWER, ON THE COLOR
,	OF Malbrana D C AVE. TYPE OF STREET Aut
r	THE PREMISES BEING LOT NO. CO. 16 1 8 0 7 7 , HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNTILES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A 9 10 earn

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.