## 5908

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED $8-13-52$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. <u>57</u>	· · · · · · · · · · · · · · · · · · ·		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	243	7'doch
WAS LATERAL AT CURBI	in disember 1995 between 1995 b	क्रमान्त्र भवति । वेत्रम् इत्याः । । । 	. /
was attached to main $\frac{y c.5}{}$	NAME OF CONTRACTOR	Remley	
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SE	RVED.	
1672 57. 5.	E,	8	•
	7-	04	
and a training the global contraction of the second of the		<b>₹</b> \	
	in film of the State the measure.	4	-78-h 243.
1 1 5 1	1100		:
SIGNED GOTEN Comment	FILED AT EN	GINEER'S OFFICE	9119157
INSPECTOR FOR CITY	នាក់ដែនកាំគឺ ១០១៩ឆ្នាំស្របំពុំវ		
REMARKS:			

## Nº 5908

## PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

i i kalanda karanda ka Marianda karanda karand	ntamija pia otoje Nesista alikali Massil	100 0000	0/23	
RECEIVED OF Ten a	e 2 das 7	Ale		2
1	1	)/0 = 1	FEE	OF \$
FOR WHICH PERMISSION IS GRANTED	8	Juan.		1
TO TAP Namelary	SEWER, ON THE		wa	<del>Tananasa.</del> Pananasakka
of 16 16 18	AVE., TYPE OF STR	EET Aan	d si	urfac
THE PREMISES BEING LOT NO. 4964		_, HOUSE NO	57	<u> </u>

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC. RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR (Confined Rember)

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.