

Nº 5912

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-8-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 643

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 131' 5' deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

CLiff ST. N.W.



SIGNED

Robert E. Hanner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9/19/52

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 5912

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/8RECEIVED OF Carl L. Hermon JrFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED sameTO TAP SanSEWER, ON THE WOF Cliff NWAVE., TYPE OF STREET dirt
ST.,THE PREMISES BEING LOT NO. 2505HOUSE NO. 613

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.