## Nº 5915

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-20-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 730		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	7. Longs
WAS LATERAL AT CURB? Yes	er er grannen i der er frankliger i der er frankliger i der er e	
WAS ATTACHED TO MAIN 1	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	·
8 TH ST. 5, W		•
	10 /	•
	And the state of t	
_	7'404/20 10	<u> </u>
and of the		e de la companya del companya de la companya del companya de la co
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	10/23/52
REMARKS:	The state of	

## Nº 5915

## PERMIT TO TAP SEWER

percent and executive to a	MASSILLO	70.70
RECEIVED OF AL. 4	The state of the s	FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED	Dangil	Veril anou
TO TAP Sanitary	Sewer, on the	east
or 81h V 32	AVE. TYPE OF STREE	oil
THE PREMISES BEING LOT NO. 3 3		HOUSE NO. 930
Work to be done in accordance		t the second sec
RULES OF THE DEPARTMENT OF PUBLI		

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.