Nº 5916

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED $9-2/-52$	• '	
DATE INSPECTED 2/-32	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 820		***************************************
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH / 26.	6 dech
WAS LATERAL AT CURBY YE	on the librariable at the months of the common weather and a series. The common of the common of	
WAS ATTACHED TO MAIN 725	- NAME OF CONTRACTOR DIAHOL	t _k
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
Euchuld Ave	. 5. W	
	1 710-7	
		164 0 126
SIGNED John Ehr	33.41	American State of the Control of the
INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE	-10/23/52_
REMARKS:	មិន្រែកស៊ីកាមស៊ី។ មាន មេសម៉ូនីពួក ស ក្នុងថា មិនជានិស ស៊ីអម្មស 	

Nº 5916

OFFICE OF THE DIRECTOR OF PUBLIC SERVIC PERMIT TO TAP SEWER

Massillon, Ohio,	10 .
RECEIVED OF a g Louisa	FEE OF \$ 2.0
FOR WHICH PERMISSION IS GRANTED E.S. Montamer	kommunika na matala kalendaria. M
TO TAP Sanitary SEWER, ON THE	t
of Eurlid & W. AVE. TYPE OF STREET OF	el mariamento de la constantida del constantida de la constantida del la constantida del constantida d
THE PREMISES BEING LOT NO. 13263 , HOUSE NO.	820
3258	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PAS	SED BY THE CITY COUN
Buy so on the Benefit of Public Struct	•

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.