Nº 5919

REMARKS: _

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-18-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 706		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DESCRIPTION STREAM TO DITCH AT CURB LINE AND DEPTH	716 dech
WAS LATERAL AT CURB?	and the second s	<i>F!</i>
WAS ATTACHED TO MAIN 125	- NAME OF CONTRACTOR Diana	
	TERAL TO WALL OF BUILDING SERVED.	····
ERIE, ST	W. 11 - 12 - 12 - 12 - 12 - 12 - 12 - 12	19
ama da de esta en el carrollo de la companione de la comp	The second section of the second section is a second section of the second section of the second section is a second section of the section of	6 dech
and the second of the second		ولي
		14 7.8. deep
SIGNED John Colors	FILED AT ENGINEER'S OFFICE	10 12 2 15
INSPECTOR FOR	CITY	
	人名英格兰 电电子电子 医二甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基	

Nº 5919

PERMIT TO TAP SEWER

Massillon, Ohio,	et 10 :
RECEIVED OF A. J. Deand	FEE OF \$ 2.0
FOR WHICH PERMISSION IS GRANTED Months of Man	-
TO TAP Sanitary SEWER. ON THE East	
OF MOUL GIL ST., TYPE OF STREET OLL	d
THE PREMISES BEING LOT NO. 76/0, HOUSE NO. 7	106
Work to be done in accordance with Ordinance No. 2323, duly passed Rules of the Department of Public Service.	BY THE CITY COUN
ROLLS OF THE BEARTMENT OF TOBLIC SERVICE.	

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.