FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-3-52 HOUSE NO. 48-14 1804	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	. 6. decl
WAS LATERAL AT CURBY VEC	i u u u u u sutre iru su errer e spelare, si popul. La compania	
WAS ATTACHED TO MAIN	TAME OF CONTRACTOR	
StonerR		
	Light Commission Light Commission and Commission and Commission Co	75-68
ine propincial mean exception and considerable of the second section of the second second second second second		40/
	301	6
SIGNED John Enni	FILED AT ENGINEER'S OFFICE	1/23/53
REMARKS:	Provide voi Control de Africa de pariblicat de celtare	

Nº 5923

PERMIT TO TAP SEWER

MASSILLON, OHIO, 16/10
RECEIVED OF a land FEE OF \$
FOR WHICH PERMISSION IS GRANTED ONCE TO Lick
TO TAP Lanitary SEWER, ON THE north
of Stone no AVE. TYPE OF STREET dut
THE PREMISES BEING LOT NO. 8017 , HOUSE NO. 1807
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COURULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR a 9 Dianel

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.