## Nº 5925 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-27-5	2 IF SO HOW AND LOCATION FROM	
HOUSE NO. 1446	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH / 09	7' du
WAS LATERAL AT CURB? YES	· · ·	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	UPER
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.	
	100 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	dup
	7'Lup	
<b>.</b>	1 Julian State of the state of	09'
SIGNED ONN EM	FILED AT ENGINEER'S OFFICE	22-52
INSPECTOR FOR	CITY BET SENTENDRE EL STREET EL MERCHE LE VIEUN	A.
11 HIGH 1120,	THE RESERVE OF THE PARTY OF THE	<i>,</i>

14-34

## Nº 5925

## PERMIT TO TAP SEWER

RECEIVED OF C. M.	euber	SILLON, OHIO, Y	FEE OF \$
TOR WHICH PERMISSION IS GRANTED	C. Dent	eer	
TO TAP Sanitan	SEWER, ON TH	e east	
of General State of S	AVE. TYPE OF S	TREET	ut
HE PREMISES BEING LOT NO.	6	, HOUSE NO	1446
		, <u></u>	

NAME OF CONTRACTOR C. Waufeen

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.