

Nº 5931

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 12-28-52 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED 6"



DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 159' 6.

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR A Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Luoy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

Cleveland
1-9-53
HP

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5931

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/8RECEIVED OF A. J. DianaFEE OF \$ 2.6FOR WHICH PERMISSION IS GRANTED Mrs. Maragie TarentTO TAP SanitarySEWER, ON THE westOF Cleveland Ave. SW.AVE.
ST.TYPE OF STREET dirtTHE PREMISES BEING LOT NO. ~~4164~~ 4164HOUSE NO. ~~1019~~ 1101WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.NAME OF CONTRACTOR A. J. Diana

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.