## Nº 5939

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

HOUSE NO. 18		D LOCATION FROM E DOWN STREAM		
SIZE OF PIPE USED	DISTANCE FROM		10'	9' dees
WAS LATERAL AT CURE?	Yes	ingszag na szere gereset *		
WAS ATTACHED TO MAIN	NAME OF CO	and the second s	A.J. D121	7 7
SHOW BY DIAGRAM RELATION	ON OF LATERAL TO WALL (	of Building Served.		
ava ing sa mga mga mga mga mga mga mga mga mga mg			60.	
				18/
SIGNED LINGTE	CIUR FOR CITY	FILED AT ENGINEE		1-109 - 52
REMARKS:		dairfriant Qpalitie	rijî în rijerri T	Am One

## Nº 5939

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO. $\mathcal{N}\mathcal{O}^{\mathcal{C}}$	-18
u	RECEIVED OF a g 20 cana	FEE OF \$
	FOR WHICH BERMISSION IS GRANTED IMPOSSED	
	TO TAP Sanitary SEWER, ON THE last	
	of Coverty nt AVE. TYPE OF STREET Dave	
ファ	THE PREMISES BEING LOT NO. 8776 + 978777, HOUSE NO. 18	34
	Work to be done in accordance with Ordinance No. 2323, buly passed by	
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	•
	NAME OF CONTRACTOR Q 9 Diama	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.