## Nº 5943

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 12 - 3 - 5 2	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO	en de la companya de La companya de la co	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	9'00
WAS LATERAL AT CURBY VES	and the second s	
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR D. BOGEY	
	TERAL TO WALL OF BUILDING SERVED.	
The state of the s	4'	
	/ Th'dee	10
a daga da wasan karangan bada ng Subali ng	and the second of the second o	•
	1/6'xq'leep	
	1/6 24	
(1, 0,-	De la	
SIGNED BLOY BOX	FILED AT ENGINEER'S OFFICE	2-11-5.
INSPECTOR FOR	cory do es denvivos o confermalistas incidentes a vitor o seguina	

## Nº 5943

## PERMIT TO TAP SEWER

Massillon, Ohio.	12/3/52
RECEIVED OF HA Plackett	
FOR WHICH PERMISSION IS GRANTED	en en en egyptikke med klassen en e
TO TAP SEWER, ON THE	).07.h
OF AVE. TYPE OF STREET	Spart Com
THE PREMISES BEING LOT NO. 806 C. HOUSE N	1804
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY	PASSED BY THE CITY COUNC
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	And the second s

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.