

14-42

Nº 5950

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 12-10-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

189'

HOUSE NO. 410

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? at Prop. Line

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-31-52

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 5950 PERMIT TO TAP SEWER

MASSILLON, OHIO,

12-23

RECEIVED OF

Ray Penley

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

Thomas B. Lundy

TO TAP

Sanitary

SEWER, ON THE

East

OF

Washington Ave.

AVE.,
ST.,

TYPE OF STREET

St.

THE PREMISES BEING LOT NO.

10784

HOUSE NO.

410

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Penley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.