

Nº 5959

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.**

DATE INSPECTED 6-16-82

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 820

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 12-27-52

REMARKS:



Nº 5959

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12 - 23

RECEIVED OF

Ray Remley

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

Frank Blunt

TO TAP

Sanitary

SEWER, ON THE

north

OF

Wall St. SE

AVE.,
ST.,

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

10043

HOUSE NO.

820

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.