

Nº 5960

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-16-52

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 11 Y' 180'

HOUSE NO. 836

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR R. Penley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED John Elmer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 12-27-52

REMARKS: \_\_\_\_\_

Nº 5960

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12-23

RECEIVED OF Ray Remley FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED John W. Murphy

TO TAP Sanitary SEWER, ON THE north

OF Hall St AVE., TYPE OF STREET dirt  
ST.,

THE PREMISES BEING LOT NO. 100<sup>39</sup>~~40~~, HOUSE NO. 836

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ray Remley

Note. This permit covers work outside of building only. Any work in  
walls of building is subject to Massillon Board of Health Regulations.