

5/4/33

Nº 5971

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-16-52IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 731SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 2' 7'WAS LATERAL AT CURB? yesWAS ATTACHED TO MAIN yesNAME OF CONTRACTOR R. Penney

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.


SIGNED

John Shoner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

2-2-53

REMARKS: _____



N^o 5971

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

12-23

RECEIVED OF

Ray Remley

FEE OF \$

2.

FOR WHICH PERMISSION IS GRANTED

Root Eckenrode

TO TAP

Sanitary

SEWER, ON THE

South

OF

Franklin Rd NE

AVE.,

TYPE OF STREET

oiled

THE PREMISES BEING LOT NO.

7988

HOUSE NO.

731

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Remley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.