

11718

Nº 5975

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-21-62

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 143

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

2-2-53

REMARKS: built manhole & lateral going into manhole

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5975

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/6RECEIVED OF Ray RemleyFEE OF \$ 2.FOR WHICH PERMISSION IS GRANTED Salvation ArmyTO TAP LantauSEWER, ON THE westOF 1st StAVE.
ST.,TYPE OF STREET pavedTHE PREMISES BEING LOT NO. 1118HOUSE NO. 143

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ray Remley

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.