

~~5-15-75~~
S.R. 15-75

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

Nº 5977

DATE INSPECTED 10-17-52

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 803

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

25'

8' L



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

1-8-53

REMARKS:

D.C.

945
Nº 5977

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/6

RECEIVED OF

Ray Remley

FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED

Thomas Smith

TO TAP

Sanitary

SEWER, ON THE

west

OF

29th St NW
Hemlock St NW

AVE.,
ST.,

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

11080

HOUSE NO.

803

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.