Nº 5978

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED /1-13-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 25 22		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 2/2	7'02
WAS LATERAL AT CURB? Y-ES	The second of th	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	jaNa
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	1
	A service of the serv	
		7 deepo
	A service and see the introduced from the bounds.	
	1/27'	sup and
SIGNED LINON KONTA	FILED AT ENGINEER'S OFFICE	MainLine
REMARKS:	Trolliemić vitojam či polifici ir sliga 🧸 .	1 1/0 3 1

5978

PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

	MASSILLON, OHIO, $\frac{16/53}{1}$
	RECEIVED OF 1- Mana FEE OF \$2-
2	FOR WHICH PERMISSION IS GRANTED all h Fadden
	TO TAP SUMMER SEWER, ON THE MOTH
Ĉ,	OF Jank and Ser. TYPE OF STREET piled
	THE PREMISES BEING LOT NO. 10964 , HOUSE NO. 2572
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.