Nº 5985

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED	2-19-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO	129		
SIZE OF PIPE USED	اں "ا	DISTANCE FROM FIRST MANHOLE P BETT STREAM TO DITCH AT CURB LINE AND DEPTH S'	D
WAS LATERAL AT	CURBI YES	in a Militinia en en estado en estado en estado en estado en entre en entre en entre en entre en entre en entre En entre en	
WAS ATTACHED TO	MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM	M RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
		18' 12' Deep	
	-N		
		CURB 128,00	
G	19	5#: 5 #: 5 #: 5 #: 5 #: 5 #: 5 #: 5 #:	
SIGNED	INSPECTOR FOR CIT	Total and Filed at Engineer's Office 3/6/93	
REMARKS:			

Nº 5985 PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

en e	in the second of		2/19
RECEIVED OF	O Mian	MASSILLON, OHIO,	
	ANTED Cmi	P / Jom	inich
TO TAP land	any sewer.	ON THE	west
of 23 and 1	MA. AVE. TYPE		ilou
THE PREMISES BEING LOT NO	3728	, HOUSE NO	129

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.