6

N? 5996

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-2-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 245		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8'
WAS LATERAL AT CURBY YES	M. P. Miller, Phys. Rev. Lett. 1997, 1997, Phys. Rev. B 1997, 1997, 1997, 1997, 1997, 1997, 1997, 1997, 1997.	
WAS ATTACHED TO MAIN	· · · · · · · · · · · · · · · · · · ·	per
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
		141
		4 deep
	/ South	
		13 Elect
		- 141.
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	
REMARKS:	ing Confident to graph of the Carlonian (

Nº 5996

OFFICE OF THE DIRECTOR OF PUBLIC SERVIC PERMIT TO TAP SEWER

A CONTRACTOR OF THE CONTRACTOR	, оню. 3-16-53
RECEIVED OF Chet Keuper	FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED CAT Keyler	
TO TAP Arani Jan SEWER, ON THE	
OFAVE., TYPE OF STREET	•
THE PREMISES BEING LOT NO. // O 55 H	OUSE NO. 245
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	, DULY PASSED BY THE CITY COUNC
News or commence Cold House and	

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.