FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED	246	FIRST MANHOLE COMPUSTRE		
HOUSE NO.		DISTANCE FROM FIRST MANH	OLE COMMISSION	
SIZE OF PIPE USED	6"	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
	3/6			
WAS LATERAL AT CURE	37 <u>NO</u>			
	IN YES		or of	Imley.
WAS ATTACHED TO MAI	"	NAME OF CONTRACTOR	The state of the s	
SHOW BY DIAGRAM REI	LATION OF LAT	TERAL TO WALL OF BUILDIN	G SERVED.	$\mathcal{L}_{\mathcal{L}}$
	In the second second second second			
	makusiii	The second section of the second seco	noj vers <mark>oseosta 1976</mark>	=36leap
e de la Colonia	valendelen er	er programica por estat distribution	DALERICE PROPERTY	
		- It, before Himble		9 X
		· //	MH. UP	1 \.
			5 Treem	. I \ I wet
			TOPPES Mai	W 131\1
Contract of the contract of th	سيعب مر			
C. / e		77 FILED	AT ENGINEER'S OFFICE	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLO	он, Оню, 3-/7-53
RECEIVED OF Kay Remly	1:
FOR WHICH PERMISSION IS GRANTED Que Har	Classic FEE of 5 2 · C
TO TAP Stinelary	en T
OF Illenian 20 AVE. TYPE OF STREET	oild
4000	HOUSE NO. 1246
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.