

10-24

Nº 6012

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-8-53

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 9066908

SIZE OF PIPE USED 6"



DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 6' CURB LINE AND DEPTH 6' Deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Boyer

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature]
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 9/9/53

REMARKS: _____

2-44 10-34 10-2

Nº 6012

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4-2-53 19.

RECEIVED OF Merwin Roger FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED H H Placett

TO TAP Sanitary SEWER, ON THE east

OF 8th st NE AVE., TYPE OF STREET front

THE PREMISES BEING LOT NO. 5308-09, HOUSE NO. 906 & 90

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Merwin Roger

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.