

19-22

Nº 6014

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-6-53

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1318

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

143'

10' deep


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

J. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4/9/53

REMARKS:

14-2
N^o 6014

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, April 11 1920

RECEIVED OF John Whitely FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Same

TO TAP San SEWER, ON THE 77

OF W. H. E. AVE., TYPE OF STREET Land
ST., San

THE PREMISES BEING LOT NO. Pl. 9K 59, HOUSE NO. 1318

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Ramsey

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.