Nº 6018

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED	4-15-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO.	5 3		
SIZE OF PIPE USED	4	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 36	6' DEEP
WAS LATERAL AT CU	IRBI YES	and the state of t	•
WAS ATTACHED TO N		NAME OF CONTRACTOR AND	nt P. Pinge
SHOW BY DIAGRAM F	RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.	
			10'
	<u> </u>	The result of the second secon	42,
		e o la la la Sula da Maria la massa en este <u>ne mesti de la c</u> erc	111 lide
SIGNED #	INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 4/3	1
REMARKS:			

Nº 6018

PERMIT TO TAP SEWER

•	MASSILLON, OHIO. 4/3/	53 ₁₉
<u>,</u>	RECEIVED OF Herbert holt FEI	of s 2 "
	FOR WHICH PERMISSION IS GRANTED I CHILL A hart	
_و	TO TAP SAME COM SEWER, ON THE	est
	OF ANE TYPE OF STREET	urfac
. 1	THE PREMISES BEING LOT NO, HOUSE NO	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR TO any Motion & Vaul Rengles

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.