

Nº 6023

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-23-53

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 427

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____



5.5' Deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR Urban & Pingree

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

J. Kathan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

8-29

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
Nº 6023 PERMIT TO TAP SEWER

th

MASSILLON, OHIO, 4/22 1915
RECEIVED OF Urban + Ringley FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Robert Worth

c.

TO TAP San SEWER, ON THE W.
OF 17th St. E. AVE., TYPE OF STREET Hard surface

THE PREMISES BEING LOT NO. 90th HOUSE NO. 127

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Urban + Ringley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.