Nº 6026

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-9-3	if so how and location from first manhole down stream	
HOUSE NO	FIRST MANHULE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	9/000
WAS LATERAL AT CURB?	<u>. S Marina di Arabana di Arab</u>	esy in the second
	NAME OF CONTRACTOR	uban .
SHOW BY DIAGRAM RELATION O	F LATERAL TO WALL OF BUILDING SERVED.	
		4"
ing the same of the same of the same	<u>. Anno en la companya de la company</u>	/>
	 A second of the contract of the c	
44	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	10'19'dup
SIGNED INSPECTOR	FILED AT ENGINEER'S OFFI	CE
	High the tree of an eastern of rediction to dis	4.4.ty

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio, 📉 🦰	<u>- 5 319</u>
2 RECEIVED OF Wm Kneppler	EE OF S
FOR WHICH PERMISSION IS GRANTED Ringly 4 Wilan	
+	
face TO TAP SEWER, ON THE LOS	
OF 23 nd M. 91) AVE., TYPE OF STREET Nound SI	
THE PREMISES BEING LOT NO. 7984 , HOUSE NO.	2

NAME OF CONTRACTOR WAY OF THE TOTAL

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.