Nº 6027

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-7-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 68		-
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7'0ex
WAS LATERAL AT CURB? YES	in the second of	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Ulban	
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.	
 And the second problems of the second second		
	\mathcal{N}	_
and was part a mile and in the	to our serious terms of the state of the sta	
	is the vicinity of a majority of the first through some of the second of	i.
	e e e e e e e e e e e e e e e e e e e	
	- Laurence de la company de la)
	141	
SIGNED A BOLLACY	FILED AT ENGINEER'S OFFICE	
INSPECTOR FOR	CITY TO BE THE THE REST OF STREET ST	
REMARKS:		

$\sim N_{\odot}^{0} \sim 6027$

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	Chlon a	wel Ringley	/ FEE OF \$
$\mathcal W$ outwood. For which permission	MONK. IS GRANTED CLIL	and Kunch	-KM.
TO TAP <u>13/13/13</u>		EWER, ON THE	
DF 2 2 200 Y		TYPE OF STREET	and the second second second
	F NO. 7730	, HOUSE NO	
		NANCE No. 2323, DULY PAS	:

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.