

Nº 6028

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-13-53

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 3123

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 15-7' 7' Deep

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR Quana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

[Signature]
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

9-8-

Nº 6028

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, May 8 1915

RECEIVED OF Howard F Dutton FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED Howard F Dutton

TO TAP Sanitary SEWER, ON THE south
OF Lincoln Way N.W. AVE., TYPE OF STREET blacktop
ST.,

THE PREMISES BEING LOT NO. 10232 HOUSE NO. 3123

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Diana

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.