

Nº 6031

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-15-53

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 153

SIZE OF PIPE USED 6"




DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 34' 8' deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED A. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

9-5

No. 6031

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, May 15 1915

RECEIVED OF

Haban & RingleyFEE OF \$ 2.0

FOR WHICH PERMISSION IS GRANTED

Don Woods

TO TAP

Sanitary

SEWER, ON THE

West

OF

27th StAVE.,
ST.,

TYPE OF STREET

oiled

THE PREMISES BEING LOT NO.

3682

HOUSE NO.

153

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Haban & Ringley

gley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.