Nº 6034

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

| DATE INSPECTED 6-2-53 | IF SO HOW AND LOCATION FROM TOPPED 307 |
|---|---|
| HOUSE NO. 15 6 0 | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURBI | |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR Alland |
| SHOW BY DIAGRAM RELATION OF LATE | RAL TO WALL OF BUILDING SERVED. |
| | |
| and a section of the | |
| • | - Jan'de |
| SIGNED AN HOLE | FILED AT ENGINEER'S OFFICE |
| (INSPECTOR FOR CIT | |
| REMARKS: | · · · · · · · · · · · · · · · · · · · |

Nº 6034

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | MASSILLON, OHIO, 5 15 -5 3 18 |
|-----|---|
| | RECEIVED OF A. I Diana FEE OF 5 2 0 |
| | (Ille Carnes) |
| . ; | FOR WHICH PERMISSION IS GRANTED |
| | TO TAP SEWER, ON THE LOST |
| | OF. Marlyn Jaceway AVE., TYPE OF STREET dist |
| | THE PREMISES BEING LOT NO. 16780 , HOUSE NO. 1500 |
| | , nouse No. |
| | Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counci |
| | RULES OF THE DEPARTMENT OF PUBLIC SERVICE. |
| | |

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.