Nº 6037

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-23-5-3	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI NO	in the Control of the American Control of the American American Control of the Co
WAS ATTACHED TO MAIN Ves	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATER	
	10'
	Section is an absence of the Administration of the West Section (1) and the Section of the Secti
	7/839' N
SIGNED A MARKS:	FIRED AT ENGINEER'S OFFICE

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE Nº 6037 PERMIT TO TAP SEWER

			ra na policina	MASSILLON, O	HIO, 5 -/	<u>/5 - 5 3 ₁₉</u>
	RECEIVED OF	1.9	Deana			FEE OF \$_2 · (
	HICH PERMISSIO		armana and the first terms of the party of the contract of the	Smith		
то тар	Santa	M	SEWEF	R. ON THE	2outh	
OF	Tremont	4	to the employed and attended to		asok	alt
THE PR	EMISES BEING L	OT NO. (4)	133	, Hous	5E NO. /8	53
Work	TO BE DONE IN	ACCORDANCE	WITH ORDINANO	E No. 2323, D	ULY PASSED B	Y THE CITY COUNCIL
RULES	OF THE DEPART	MENT OF PUBL	IC SERVICE.			
Name	OF CONTRACTOR	1. 9	Diam			

Note. This permit covers work outside of building only. Any work ir walls of building is subject to Massillon Board of Health Regulations.