15-18

Nº 6048

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED	6-4-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2	34		
SIZE OF PIPE USED	600	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH L2	8' 10881
WAS LATERAL AT CURB	· Ves		
WAS ATTACHED TO MAI	<i>t</i> = -	NAME OF CONTRACTOR C Re	uper
SHOW BY DIAGRAM REL	ATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
and the second of the second o	^		15'
		and the second of the second o	Tolap
	>		5/3
		in the self of the property are as a complete few over the complete few beautiful for	ام. /تم
		unut kasa di satuk tina mesta penditu tahun beraselta. T	/ July
			19271
	10		
SIGNED LLO	1 Douther	W	
	NSPECTOR FOR CIT	Y (1) Shows if any confidence is a likely of the short	
REMARKS:			

15-18

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

·	n e en si a espetitiva de si La entre en 100 en en este esp	torigin, volte er volte Cod Ale Hald Total Code	Massillon	. Оню	May 2	ð. ''
RECEIVED OF	CRIT	Kengar				
FOR WHICH PERMISS	FON IS GRANTED	CLI	King	Contract		
то тар Аст	clac	SEWEF	R, ON THE		Z	agedd (f. 16) Saeges
of Hail	ne	AVE., TYP	E OF STREET.	di	it	
THE PREMISES BEING		1/053	2.0		234	
WORK TO BE DONE RULES OF THE DEPA			E No. 2323,	DULY PASS	SED BY THE CITY	Counci

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.

Cht Keysen