## Nº 6051

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED <u>6-27-53</u>	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 832		
SIZE OF PIPE USED 4/11 VF	DISTANCE FROM FIRST MANHOLE DESCRIPTION STREAM TO DITCH AT CURB LINE AND DEPTH	5'deep
WAS LATERAL AT CURBI YES	and the state of t	- V A
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	18 Ringly
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.	0 []
and the control of th	a1	
taling and the second of the s		6'deep
recommendation of the second s	and the second s	
$\leftarrow V$		Ns'deep
SIGNED LAWY LATE	50'	
REMARKS:	FILED AT ENGINEER'S OFFICE	

11-388

## Nº 6051

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Ohio,	5-27
\$4.	RECEIVED OF Rengly & Untan	FFE OF C
J	FOR WHICH PERMISSION IS GRANTED	hi
1 hass	TO TAP SANGER SEWER, ON THE	s T
y and	OF Phillips DE AVE. TYPE OF STREET !	and sunface
	THE PREMISES BEING LOT NO. 5 9 4/5 HOUSE N	o. <u>832</u>
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY	PASSED BY THE CITY COUNCIL

,Na

NAME OF CONTRACTOR War & Fungley

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.