

7-24

Nº 6055

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-4-53IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 316SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH117' 6' DeepWAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Urban & Ringley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N ←



SIGNED

R. J. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

7-29-32

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6055

PERMIT TO TAP SEWER

RECEIVED OF Lerhan + Ringley MASSILLON, OHIO, 6/3 1932
FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED 1st West

TO TAP San SEWER, ON THE E

OF 21st West AVE., TYPE OF STREET East

THE PREMISES BEING LOT NO. 7215 HOUSE NO. 316

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Lerhan + Ringley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.