

Nº 6056

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-3-53

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 812

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

65' 5' Deep.


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Urban & Ringley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. J. Snyder

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

4-13-14

No 6056

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/5

RECEIVED OF

Urban & Ringley

FEE OF

2.00

FOR WHICH PERMISSION IS GRANTED

R. E. Johnson

TO TAP

San

SEWER, ON THE

South

OF

Cherry Tree

AVE., TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

9737 9739

HOUSE NO.

873 81

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Urban & Ringley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.