\mathbf{N} ? 6073

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

運搬をプレートライン・フェノー・ケス	•	
DATE INSPECTED / / /)	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 300	THE WANNELD DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8'deep
WAS LATERAL AT CURB? YCS	in die gewone der der der der der der der der der de	
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR	1 Viana
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
	A STATE OF THE STA	124
		110
A	,	
kali ayub uga kilasee ja 🏒 bebb 🔥	And the creek to control section and restricted the control of the control of	A STATE OF THE STA
	าง 🥠 และสายสาราว สาราชาวาสาราชาวาสาราชา	guerra di 🛴 📈 . T
		MI
		1 del
and the state of t		418 des
\mathcal{G}	41	
SIGNED AUTH NOL	Cham FILED AT ENGINEER'S OF	FICE
INSPECTOR/FOR C	ry I cediteas ha los locitibe el telibilid le la	the state of the s
REMARKS:		

19-97 14=4/8

Nº 6073 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohjo,	6/20/53 11
RECEIVED OF albert Conner	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	
TO TAP SEWER, ON THE LOS	
OF 23 at 17 . 21 AVE. TYPE OF STREET	in your the second of
THE PREMISES BEING LOT NO. 370/, HOUSE NO.	#
Work to be done in accordance with Ordinance No. 2323, duly pas	SED BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.